



EXECUTIVE OFFICE

10949 North Mather Boulevard, Rancho Cordova, CA 95670

P (916) 403-8600 F (916) 464-3424 I www.bar.ca.gov



[Redacted]  
[Redacted]  
[Redacted]  
[Redacted], CA [Redacted]

ARD/TC [Redacted]

Re: Decision on Proposed STAR Invalidation, OVERTURNED

[Redacted]

On [Redacted], the Bureau informed you that your station's STAR certification is subject to invalidation pursuant to section 3392.5.1 of Title 16 of the California Code of Regulations (CCR) for failure to meet one or more of the STAR Program performance measures.

On [Redacted] the Bureau received a request from your station for a hearing on the proposed STAR invalidation. The request for a hearing contained information or arguments contrary to the proposed invalidation.

On [Redacted], at the Bureau's headquarters, located at 10949 North Mather Boulevard, Rancho Cordova, California 95670, the above referenced matter was reviewed by Michael Lafferty of the Bureau of Automotive Repair, who is authorized as the Chief's designee under CCR section 3392.6.1 to issue a decision on this matter.

Based on a thorough review of your station's performance reports and due consideration given to the information provided, the cause(s) for invalidation are not confirmed and the proposed invalidation of the STAR certification of your station is **overturned**. Your station may continue to operate as a STAR certified station.

For continued updates and information about the STAR Program, please visit the BAR website at [www.smogcheck.ca.gov](http://www.smogcheck.ca.gov). The website has definitions of STAR terms, frequently asked questions, and a detailed explanation of the various STAR performance measures.

Respectfully,

Michael Lafferty  
Program Manager II  
Bureau of Automotive Repair

cc: Licensing Unit

cc: Mr. William D. Ferreira, Esq.  
582 Market Street, Suite 1608  
San Francisco, CA 94104